

Vulnerability Disclosure

CVE-2023-23594: Insufficient Access Controls - Web GUI (FIXED)

SATO America was made aware of a vulnerability in some versions of the printer firmware that could falsely allow unauthorized users to access printer web configurations with a simple authentication bypass. The firmware has been upgraded to unauthorize when improper authorization methods are sent.

For more information about printer firmware version and supported model, please [contact us](#).

Credit: This issue was discovered by the Lockheed Martin Red Team and validated by SATO America engineering team.